



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-1

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Dry to 12". Some roots.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:13	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. At 2.25', moderate yellowish brown (10YR 5/4) to moderate brown (5YR 3/4).			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:14	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:15	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%. Trace amount of Silt. Moderate yellowish brown (10YR 5/4).			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-2

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Dry to 12".			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:22	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. At 2.25', moderate yellowish brown (10YR 5/4) to moderate brown (5YR 3/4).			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:23	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:24	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%. Trace amount of Silt. Moderate yellowish brown (10YR 5/4).			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-3

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:34	90	0.0/0.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. At 2-5', mottling, moderate brown (5YR 3/4) to moderate yellowish brown (10YR 5/4).			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:35	90	0.0/0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:36	90	0.0/0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-4

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface			
				TOPSOIL Loamy Topsoil. Dark Brown. Dry to 18".		0	
6"-12"	8:47	90	0.0/0.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
<i>Soil Sample Submitted for Lab Analysis.</i>							
2-2.5	8:48	90	0.0/0.2			2	
<i>Soil Sample Submitted for Lab Analysis.</i>							
3.5-4	8:49	90	0.0/0.1			4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				<div></div> End of Boring			
						6	

2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-5

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:53	90	0.0/0.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 4" layer of topsoil at 2'. Moist at 2-3.5'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:54	90	0.0/0.2				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:55	90	0.0/0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-6

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:07	90	0.0/0.2	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 5" layer of Topsoil at 3.5-4'.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:08	90	0.0/0.1				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	9:09	90	0.0/0.1	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-7

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	9:15	90	0.0/0.4	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
						2	
2-2.5	9:16	90	0.0/0.2				
3.5-4	9:17	90	0.0/0.1			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-8

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:23	90	0.0/0.6	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Topsoil from 3-3.5'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:24	90	0.0/0.4			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	9:25	90	0.0/0.1	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-9

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Dry to 12".			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:50	90	0.0/0.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. At 3.25-3.75', Silt 40%. Gray and black hue.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:51	90	0.0/0.1				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	9:52	90	0.0/0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-10

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:58	90	0.0/0.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. At 2.75-3', Silty Topsoil.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:59	90	0.0/0.2			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:00	90	0.0/0.1			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-11

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	10:05	80	0.0/0.2	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. At 3.25-3.5', a 3" layer of Topsoil.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	10:06	80	0.0/0.2				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:07	80	0.0/0.2	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-12

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:11	80	0.0/0.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
						2	
2-2.5	10:12	80	0.0/0.1				
3.5-4	10:13	80	0.0/0.2			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-13

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	10:24	90	0.0/0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 1" layer of Topsoil at 3'.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	10:25	90	0.0/0.1				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:26	90	0.0/0.1	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-14

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	10:30	90	0.0/2.1	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 3" layer of Topsoil at 3'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	10:31	90	0.0/4.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:32	90	0.0/2.7	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-15

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	10:36	90	0.0/0.8	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A .5" layer of Silty Topsoil at 2.75'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	10:37	90	0.0/1.4			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:38	90	0.0/2.1	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-16

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:51	80	0.0/1.7	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
						2	
2-2.5	10:52	80	0.0/2.5				
3.5-4	10:53	80	0.0/2.7			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40





BORING NUMBER: B-17

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Dry to 8".			
6"-12"	10:57	80	0.0/2.7	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
Soil Sample Submitted for Lab Analysis.							
2-2.5	10:58	80	0.0/2.8			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	10:59	80	0.0/2.5			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
							
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-18

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	11:03	90	0.0/4.2	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	11:04	90	0.0/5.2			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	11:05	90	0.0/2.1	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring		6	



***Project Number:* 11-10378-40**

***Date:* 7/10/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Little to no Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	11:08	80	0.0/6.7	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Silty to 4.25'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	11:09	80	0.0/4.9				
						2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	11:10	80	0.0/3.5			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				----- End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-20

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:02	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 4" layer of Topsoil at 3'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:03	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:04	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-21

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Dry to 12-14".			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:10	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 4" layer of Topsoil at 2.5'.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:11	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:12	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-22

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:15	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:16	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:17	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-23

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:21	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Small rock at 3.25'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:22	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:23	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenviromental.net

Project Number: 11-10378-40




BORING NUMBER: B-24

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel at 0-6".			
6"-12"	13:42	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
<i>Soil Sample Submitted for Lab Analysis.</i>							
2-2.5	13:43	90	0.0			2	
<i>Soil Sample Submitted for Lab Analysis.</i>							
3.5-4	13:44	90	0.0			4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				<div><div></div></div> End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenviromental.net

Project Number: 11-10378-40




BORING NUMBER: B-25

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel at 0-6".			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:49	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Silt 40% from 3.25-3.75'. Moderate yellowish brown (10YR 5/4) to dusky yellowish brown (10YR 2/2).			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:50	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:51	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



www.robertsenvironmental.net

***Date:* 7/10/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:54	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Silt 20% from 3-3.5'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:55	90	0.0				
						2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:56	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				<div></div> End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenviromental.net

Project Number: 11-10378-40




BORING NUMBER: B-27

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel at surface.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	14:00	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	14:01	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	14:02	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-28

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel at surface.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	14:13	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	14:14	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	14:15	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-29

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel at surface.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	14:18	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	14:19	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	14:20	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-30

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/10/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	14:25	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some Iron staining at 3.25-5'.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	14:26	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	14:27	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenviromental.net

Project Number: 11-10378-40




BORING NUMBER: B-31

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:15	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. A 6" layer of Topsoil at 2-2.5'. Trace amount of Silt at 3-5'.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:16	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:17	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-32

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:21	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Silt 20% at 2.5-4'.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:22	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:23	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-33

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:27	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Dark Brown. Less Topsoil at 2-2.75'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:28	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:29	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-34

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:34	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:35	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:36	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenviromental.net

Project Number: 11-10378-40




BORING NUMBER: B-35

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	8:53	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Silty from 0-3.75'.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	8:54	90	0.0			2	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	8:55	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



Project Number: 11-10378-40




***Date:* 7/16/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:04	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:05	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:06	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring		6	



***Project Number:* 11-10378-40**




***Date:* 7/16/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	Well Completion
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:10	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	12:11	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some Iron mottles.			
Soil Sample Submitted for Lab Analysis.							
3.5-4	12:12	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



www.robertsenvironmental.net




***Date:* 7/16/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:16	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	12:17	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	12:18	90	0.0				4
<i>Soil Sample Submitted for Lab Analysis.</i>							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



www.robertsenvironmental.net




***Date:* 7/16/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:22	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:23	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:24	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				----- End of Boring			
						6	



www.robertsenvironmental.net

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:36	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:37	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:38	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				----- End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-41

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/16/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:43	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:44	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:45	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



***Project Number:* 11-10378-40**

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Sandy Topsoil from 0-3.75'.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:58	90	0.0				
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:59	90	0.0				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:00	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-43

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Silty Topsoil from 0-3.75'.			
6"-12"	10:16	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	10:17	90	0.0				
Soil Sample Submitted for Lab Analysis.							
3.5-4	10:18	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



***Project Number:* 11-10378-40**

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:22	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	10:23	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
3.5-4	10:24	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-45

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:28	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	10:29	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	10:30	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring		6	



Project Number: 11-10378-40

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	10:46	90	0.0				
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	10:47	90	0.0		2		
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	10:48	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-47

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:52	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	10:53	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	10:54	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-48

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:57	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	10:58	90	0.0				
Soil Sample Submitted for Lab Analysis.				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	10:59	90	0.0			4	
Soil Sample Submitted for Lab Analysis.				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-49

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	11:03	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	11:04	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	11:05	90	0.0				
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-50

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	11:53	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	11:54	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	11:55	90	0.0				
				End of Boring			
						6	



www.robertsenvironmental.net

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	11:58	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		2	
2-2.5	11:59	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
3.5-4	12:00	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						4	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-52

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel.			
6"-12"	12:04	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	12:05	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	12:06	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-53

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:09	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:10	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:11	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring		6	



Project Number: 11-10378-40

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:26	90	0.0				
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:27	90	0.0		2		
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:28	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-55

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN





Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:32	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	12:33	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Iron mottling from 2.75-4.5'.			
3.5-4	12:34	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



***Project Number:* 11-10378-40**

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:37	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:38	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:39	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				 End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-57

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:43	90	0.0				
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:44	90	0.0			2	
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some Iron mottles.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:45	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-58

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	13:04	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	13:05	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4	13:06	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-59

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN





Date: 7/11/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	13:10	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	13:11	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4	13:12	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				End of Boring		6	



www.robertsenvironmental.net





***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion	
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth		
				Ground Surface		0		
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.				
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:16	90	0.0					
						2		
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:17	90	0.0					
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.				
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:18	90	0.0					4
				 End of Boring				
						6		



***Project Number:* 11-10378-40**

***Date:* 7/11/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:22	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:23	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:24	90	0.0				
							
				End of Boring			
							6



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-62

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	8:25	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	8:26	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
3.5-4	8:27	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-63

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	8:31	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	8:32	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
3.5-4	8:33	90	0.0			4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-64

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012





SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	8:37	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	8:38	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%. Some Iron mottles at 3.25-5'.			
3.5-4	8:39	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				End of Boring			
						6	



***Project Number:* 11-10378-40**

BORING NUMBER: B-65




***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	8:43	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	8:44	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
3.5-4	8:45	90	0.0			4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
							
				End of Boring			
						6	



Project Number: 11-10378-40




***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown. Some Gravel at surface.			
6"-12"	9:01	90	0.0				
2-2.5	9:02	90	0.0		2		
3.5-4	9:03	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				----- End of Boring			
						6	



***Project Number:* 11-10378-40**

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	9:08	90	0.0				
2-2.5	9:09	90	0.0				
3.5-4	9:10	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



Goshen, Indiana

www.robertsenvironmental.net

Client: Barnes & Thornburg

Location: Elkhart, IN

Page: 1 of 1



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-69

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	9:21	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some Iron mottles at 3.25-5'.		2	
2-2.5	9:22	90	0.0				
Soil Sample Submitted for Lab Analysis.							
3.5-4	9:23	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-70

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:35	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some Iron mottling.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:36	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	9:37	90	0.0				
				End of Boring		6	



***Project Number:* 11-10378-40**





***Date:* 7/12/2012**

-6



www.robertsenvironmental.net




***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	9:47	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	9:48	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	9:49	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%. Some Iron mottles at 3.75-5'.		4	
							
				End of Boring			
							6



Project Number: 11-10378-40




***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	9:53	90	0.0				
2-2.5	9:54	90	0.0		2		
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	9:55	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



www.robertsenvironmental.net

***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:12	90	0.0				
						2	
2-2.5	10:13	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4	10:14	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-75

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown. Dry to 18".			
6"-12"	10:18	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	10:19	90	0.0			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	10:20	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-76

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:24	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	10:25	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
3.5-4	10:26	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				<div></div> End of Boring			
							6



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-77

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SILTY TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	10:30	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	10:31	90	0.0			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	10:32	90	0.0	SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.		4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-78

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	11:31	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	11:32	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some roots at 3'.			
						4	
3.5-4	11:33	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
						6	
				End of Boring			



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-79

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	11:37	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	11:38	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
						4	
3.5-4	11:39	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
						6	
				End of Boring			



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-80

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	11:43	80	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	11:44	80	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Some Iron mottles at 3-5'.			
3.5-4	11:45	80	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



Goshen, Indiana

www.robertsenvironmental.net

***Project Number:* 11-10378-40**




BORING NUMBER: B-81

Client: Barnes & Thornburg

***Project:* 2503 Marina Drive Property**

Location: Elkhart, IN

***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	11:49	90	0.0				
						2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	11:50	90	0.0				
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%.			
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	11:51	90	0.0			4	
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				<div>End of Boring</div>			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-82

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:09	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	12:10	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 20-30% and Fine Sand 70%. Topsoil Layer at 3-3.75'.			
3.5-4	12:11	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-83

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN




Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				SANDY TOPSOIL Loamy Topsoil. Dark Yellow Brown.			
6"-12"	12:15	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	12:16	90	0.0			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	12:17	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	



www.robertsenvironmental.net

***Date:* 7/12/2012**

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:20	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	12:21	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
3.5-4	12:22	90	0.0	SILTY/FINE SAND Silt 10-20% and Fine Sand 80%.		4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-85

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:26	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	12:27	90	0.0				
Soil Sample Submitted for Lab Analysis.							
				SILTY/FINE SAND Silt 10-20% and Fine Sand 80%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
3.5-4	12:28	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-86

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12"	12:44	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
						2	
2-2.5	12:45	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
				SILTY/FINE SAND Silt 10-20% and Fine Sand 80%.			
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
3.5-4	12:46	90	0.0			4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-87

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:50	90	0.0				
				SILTY/FINE SAND Silt 10-20% and Fine Sand 80%.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:51	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:52	90	0.0				
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-88

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	12:56	90	0.0				
				SILTY/FINE SAND Silt 10-20% and Fine Sand 80%.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	12:57	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	12:58	90	0.0				
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-89

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:02	90	0.0				
				SILTY/FINE SAND Silt 10-20% and Fine Sand 80%.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:03	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:04	90	0.0				
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40




BORING NUMBER: B-90

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown.			
6"-12" <i>Soil Sample Submitted for Lab Analysis.</i>	13:25	90	0.0				
				SILTY/FINE SAND Silt 10-20% and Fine Sand 80%. Gravel/Sand at 2-2.75'.		2	
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:26	90	0.0				
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%. Topsoil with Sand at 3-3.75'.		4	
3.5-4 <i>Soil Sample Submitted for Lab Analysis.</i>	13:27	90	0.0				
				End of Boring		6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-91

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Loamy Topsoil. Dark Brown. Dry.			
6"-12"	13:31	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	13:32	90	0.0			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	13:33	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-92

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Sandy Topsoil. Dark Brown. Dry.			
6"-12"	13:37	90	0.0				
<i>Soil Sample Submitted for Lab Analysis.</i>							
2-2.5	13:38	90	0.0			2	
<i>Soil Sample Submitted for Lab Analysis.</i>							
3.5-4	13:39	90	0.0			4	
<i>Soil Sample Submitted for Lab Analysis.</i>							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-93

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Sandy Topsoil. Dark Brown. Dry. Some roots at 4'.			
6"-12"	13:44	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	13:45	90	0.0			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	13:46	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: B-94

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/12/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				TOPSOIL Sandy Topsoil. Dark Brown. Dry.			
6"-12"	13:50	90	0.0				
Soil Sample Submitted for Lab Analysis.							
2-2.5	13:51	90	0.0			2	
Soil Sample Submitted for Lab Analysis.							
3.5-4	13:52	90	0.0			4	
Soil Sample Submitted for Lab Analysis.							
				FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%.			
				End of Boring			
						6	



***Project Number:* 11-10378-40**

***Date:* 7/13/2012**

End of Boring



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40



BORING NUMBER: B-96

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/13/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				GRAVEL/SILT Gravel with Silt. Dark Brown/Gray.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:12	60	0.0	SILTY FINE/MEDIUM SAND Silt- Trace to 10%, Fine Sand 60%, and Medium Sand 40%. Moderate yellowish brown (10YR 5/4). Wet at 3-3.5'.		2	
2.5-3 <i>Soil Sample Submitted for Lab Analysis.</i>	13:13	60	0.0				
				End of Boring		4	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40



BORING NUMBER: B-97

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/13/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				GRAVEL/SILT Gravel with Silt. Dark Brown/Gray.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:19	50	0.0	SILTY FINE/MEDIUM SAND Silt- trace to 10%, Fine Sand 60%, and Medium Sand 40%. Moderate yellowish brown (10YR 5/4). Wet at 3-3.5'.		2	
2.5-3 <i>Soil Sample Submitted for Lab Analysis.</i>	13:20	50	0.0				
				End of Boring		4	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40



BORING NUMBER: B-98

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/13/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				GRAVEL/SILT Gravel with Silt. Dark Brown/Gray.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:25	50	0.0	SILTY FINE/MEDIUM SAND Silt- trace to 10%, Fine Sand 60%, and Medium Sand 40%. Moderate yellowish brown (10YR 5/4). Wet at 3-3.5'.		2	
2.5-3 <i>Soil Sample Submitted for Lab Analysis.</i>	13:26	50	0.0				
				End of Boring		4	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40



BORING NUMBER: B-99

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/13/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
				GRAVEL/SILT Gravel with Silt. Dark Brown/Gray.			
2-2.5 <i>Soil Sample Submitted for Lab Analysis.</i>	13:31	60	0.0	SILTY FINE/MEDIUM SAND Silt- trace to 10%, Fine Sand 60%, and Medium Sand 40%. Moderate yellowish brown (10YR 5/4). Wet at 3-3.5'.		2	
2.5-3 <i>Soil Sample Submitted for Lab Analysis.</i>	13:32	60	0.0				
				End of Boring		4	



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: GW-24

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/13/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
6"-12"	9:34	90	0.0	TOPSOIL Loamy Topsoil. Dark Brown.			
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	9:35	90	0.0				
Soil Sample Submitted for Lab Analysis.							
						4	
3.5-4	9:36	90	0.0	SILTY/FINE SAND Silt 10-20% and Fine Sand 80%. Silty to 3.75'. Some Iron mottles from 4-5'.			
Soil Sample Submitted for Lab Analysis.							
						6	
Ground water samples collected 5-10', 24-28', and 36-40'.						8	
						10	
				End of Boring Ground Water Sample Submitted for Lab Analysis.			



2112 Carmen Court

Goshen, Indiana

Ph: (574) 537-0881

www.robertsenvironmental.net

Project Number: 11-10378-40

BORING NUMBER: GW-25

Client: Barnes & Thornburg

Project: 2503 Marina Drive Property

Location: Elkhart, IN

Date: 7/13/2012

SAMPLE INFORMATION				SUBSURFACE PROFILE			Well Completion
Sample I.D.	Time	Recovery (%)	FID (ppm)	Lithologic Description	Symbol	Depth	
				Ground Surface		0	
6"-12"	11:12	90	0.0	TOPSOIL Loamy Topsoil. Dark Brown.			
Soil Sample Submitted for Lab Analysis.							
						2	
2-2.5	11:13	90	0.0	SILTY/FINE SAND Silt 10-20% and Fine Sand 80%. Some Iron mottles from 4-5'.			
Soil Sample Submitted for Lab Analysis.							
						4	
3.5-4	11:14	90	0.0	FINE/MEDIUM SAND Fine Sand 80% and Medium Sand 20%. Wet at 7.25'.			
Soil Sample Submitted for Lab Analysis.							
						6	
Ground water samples collected 5-10', 24-28', and 36-40'.							
						8	
						10	
				End of Boring Ground Water Sample Submitted for Lab Analysis.			